

FIG. 1



MEASUREMENT OF RADIATION DOSE AND PRODUCTION OF RADIATION IMAGE February 2, 2001
Waddell A. Biggart 202-293-7060
2 of 7

FIG. 2



ISODA Q62998
MEASUREMENT OF RADIATION DOSE AND PRODUCTION OF RADIATION IMAGE
February 2, 2001
Waddell A. Biggart 202-293-7060
3 of 7

FIG. 3





FIG. 4



ISODA Q62998
MEASUREMENT OF RADIATION DOSE AND PRODUCTION OF RADIATION IMAGE February 2, 2001
Waddell A. Biggart 202-293-7060
4 of 7

FIG. 5






FIG. 6




ISODA Q62998
MEASUREMENT OF RADIATION DOSE AND PRODUCTION OF RADIATION IMAGE
February 2, 2001
Waddell A. Biggart 202-293-7060
5 of 7

FIG. 7



ISODA Q62998
MEASUREMENT OF RADIATION DOSE AND PRODUCTION OF RADIATION IMAGE February 2, 2001
Waddell A. Biggart 202-293-7060
6 of 7

FIG. 8






FIG. 9

